

## City of Taunton - Cost Estimation for School Buildings

**City Priorities**  
 Priority 1: Program Access  
 Priority 2: Safety  
 Priority 3: Approach and Entrance  
 Priority 4: Access to Goods and Services  
 Priority 5: Toilet or Bathing Rooms  
 Priority 6: Additional Access

**\*Cost Estimate Notes:**

- Cost of design is not included
- Does not include costs when note indicates future work
- Labor cannot be estimated for all remedies
- There is no cost noted when it's presumed to be a maintenance issue.

*Estimates are intended as a guide to budgeting access modifications and are not intended to be absolutely comprehensive or definitive.*

Information Provided by City of Taunton

[illegible]

188	Bennett Elementary School	512-056		J. Signage	A.Not provided	gym	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
189	Bennett Elementary School	512-057		J. Signage	A.Not provided	storage	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
190	Bennett Elementary School	512-058		J. Signage	A.Not provided	cafeteria	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
191	Bennett Elementary School	512-059		J. Signage	A.Not provided	gym	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
192	Bennett Elementary School	512-060		J. Signage	A.Not provided	women's locker room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
193	Bennett Elementary School	512-061		J. Signage	A.Not provided	teachers room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
194	Bennett Elementary School	512-062		J. Signage	A.Not provided	classroom 8	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
195	Bennett Elementary School	512-063		J. Signage	A.Not provided	janitor	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
196	Bennett Elementary School	512-067		J. Signage	A.Not provided	book storage 1	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
197	Bennett Elementary School	512-029		J. Signage	A.Not provided	classroom 7	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
198	Bennett Elementary School	512-032		J. Signage	A.Not provided	boys toilet room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
199	Bennett Elementary School	512-036		J. Signage	A.Not provided	girls toilet room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
200	Bennett Elementary School	512-039		J. Signage	A.Not provided	classroom 6	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
201	Bennett Elementary School	512-040		J. Signage	A.Not provided	classroom 5	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
202	Bennett Elementary School	512-043		J. Signage	A.Not provided	classroom 4	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
203	Bennett Elementary School	512-045		J. Signage	A.Not provided	classroom 3	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
204	Bennett Elementary School	512-047		J. Signage	A.Not provided	classroom 2	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
205	Bennett Elementary School	512-049		J. Signage	A.Not provided	classroom 1	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
206	Bennett Elementary School	512-054		J. Signage	A.Not provided	K-2	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
207	Bennett Elementary School	512-055		J. Signage	A.Not provided	boys	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
208	Bennett Elementary School	512-057		J. Signage	A.Not provided	girls	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
209	Bennett Elementary School	512-061		J. Signage	A.Not provided	cafeteria	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
210	Bennett Elementary School	512-067		J. Signage	A.Not provided	cafeteria	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
211	Bennett Elementary School	512-068		J. Signage	A.Not provided	switch gear	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
212	Bennett Elementary School	512-071		J. Signage	A.Not provided	men's & women's	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
213	Bennett Elementary School	512-075		J. Signage	A.Not provided	janitor	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
214	Bennett Elementary School	512-076		J. Signage	A.Not provided	classroom 9	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
215	Bennett Elementary School	512-077		J. Signage	A.Not provided	office	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
216	Bennett Elementary School	512-081		J. Signage	A.Not provided	classroom 10	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
217	Bennett Elementary School	512-082		J. Signage	A.Not provided	classroom 11	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
218	Bennett Elementary School	512-084		J. Signage	A.Not provided	book room 2	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
219	Bennett Elementary School	512-085		J. Signage	A.Not provided	classroom 12	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
220	Bennett Elementary School	512-089		J. Signage	A.Not provided	toilet room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
221	Bennett Elementary School	512-092		J. Signage	A.Not provided	classroom 13	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
222	Bennett Elementary School	512-093		J. Signage	A.Not provided	classroom 14	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
223	Bennett Elementary School	512-096		J. Signage	A.Not provided	classroom 15	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
224	Bennett Elementary School	512-098		J. Signage	A.Not provided	classroom 16	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
225	Bennett Elementary School	512-060		J. Signage	A. Not provided	agrees	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
226	Bennett Elementary School	512-093		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided	boys toilet room	Priority 5	Toilet or Bathing Rooms	Remodel toilet room to provide 2 accessible stall and 1 accessible sink.	\$4,500.00			Superintendent of Schools		
227	Bennett Elementary School	512-037		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided	girls toilet room	Priority 5	Toilet or Bathing Rooms	Remodel toilet room to provide 2 accessible stall and 1 accessible sink.	\$4,500.00			Superintendent of Schools		
228	Bennett Elementary School	512-056		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided E. Floor space space not provided in toilet room	boys	Priority 5	Toilet or Bathing Rooms	Provide signage to accessible boy's toilet room	\$150.00			Superintendent of Schools		
229	Bennett Elementary School	512-058		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided E. Floor space space not provided in toilet room		Priority 5	Toilet or Bathing Rooms	Provide signage to accessible toilet room	\$150.00			Superintendent of Schools		
230	Bennett Elementary School	512-072		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided E. Floor space space not provided in toilet room	women's	Priority 5	Toilet or Bathing Rooms	Remodel toilet room to provide 2 accessible stall and 1 accessible sink.	\$4,500.00			Superintendent of Schools		
231	Bennett Elementary School	512-073		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided E. Floor space space not provided in toilet room	men's	Priority 5	Toilet or Bathing Rooms	Remodel toilet room to provide 2 accessible stall and 1 accessible sink.	\$4,500.00			Superintendent of Schools		
232	Bennett Elementary School	512-090		B. Overall Access	A. Burning space not provided B. Accessible plumbing fixtures or stalls not provided C. Accessible Accessories not provided D. Visual & audible alarm not provided E. Floor space space not provided in toilet room	boys & girls	Priority 5	Toilet or Bathing Rooms	Provide signage directing people to accessible toilet room	\$150.00			Superintendent of Schools		
233	Bennett Elementary School	512-014		A. Drinking Fountain	A. Floor space not provided at drinking fountain	gym	Priority 6	Additional Access	Provide signage directing people to accessible drinking fountain.	\$150.00			Superintendent of Schools		
234	Bennett Elementary School	512-015		A. Drinking Fountain	A. Floor space not provided at drinking fountain	gym	Priority 6	Additional Access	Provide signage directing people to accessible drinking fountain.	\$150.00			Superintendent of Schools		
235	Bennett Elementary School	512-074		A. Drinking Fountain	A. Floor space not provided at drinking fountain	corridor	Priority 6	Additional Access	Provide at least one accessible drinking fountain for standing and seated use.	\$4,800.00			Superintendent of Schools		
236	Chamberlain Elementary	No assigned record #		J. Signage	A. Not provided	Auditorium/cafeteria	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the backside of the door.	\$150.00			Superintendent of Schools		
237	Chamberlain Elementary School	54-009		H. Curb Ramp	B. Slope 1:12 C. Curb ramps not be used properly		Priority 3	Approach and Entrance	Correct cross slope at curb ramp	\$138.25	2019	January 2018	Superintendent of Schools	completed	none
238	Chamberlain Elementary School	54-000		H. Entrance	A. Barrier not securely attached		Priority 2	Safety	Secure all weather mats with industrial-strength double-click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2018	Jan-18	Superintendent of Schools	completed	none
239	Chamberlain Elementary School	54-048		D. Interior Route	A. Barrier not securely attached	Sub-sop 2nd grade	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2018	Jan-18	Superintendent of Schools	completed	none
240	Chamberlain Elementary School	54-082		D. Interior Route	A. Barrier not securely attached B. Floor width <36"	1st fl. route to backstage lift	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances. Move furniture to provide a clear width of 36". Provide sign directing people to lift.	\$400.00	2018	Jan-18	Superintendent of Schools	completed	none
241	Chamberlain Elementary School	54-029		D. Interior Route	C. Obstructed by protruding objects	library	Priority 2	Safety	Move signage out of the circulation path or provide a cane detectable barrier.	\$50.00	2018	Jan-18	Superintendent of Schools	completed	none
242	Chamberlain Elementary School	54-005		D. Interior Route	D. Surface not stable, firm, and slip-resistant	004	Priority 4	Access to Goods and Services	Repair surface. Provide signage directing people to an accessible exit	\$450.00			Superintendent of Schools		
243	Chamberlain Elementary School	54-026		D. Interior Route	B. Floor width <36"	library	Priority 4	Access to Goods and Services	Move furniture to maintain a 36" at the door.	\$90.00	2018		Superintendent of Schools		
244	Chamberlain Elementary School	54-004 a		D. Interior Route	A. Barrier not securely attached	Sub-sop classroom	Priority 4	Access to Goods and Services	Secure all weather mats with industrial-strength double-click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$350.00	2018		Superintendent of Schools		
245	Chamberlain Elementary School	54-004 b		D. Interior Route	Door leads to outside play area. no accessible threshold no signage to accessible exit This is an emergency / fire route to road, and inaccessible outside.	Sub-sop classroom	Priority 4	Access to Goods and Services	Provide signage directing people to an accessible exit.	\$350.00	2018		Superintendent of Schools		

147	Chamberlain Elementary School	14-009	E. Service Counter	counter too high 2' downward approach - surface <0°' long	Priority 4	Access to Goods and Services	Modify counters on each office with public interface so that they are accessible. In the meantime, provide an auxiliary counter no higher than 36" above the floor in close proximity to the main counter, or provide equivalent facilitation. Equivalent facilitation may be provided in the form of a folding shelf attached to the main counter, an auxiliary table nearby, a clipboard made available to the public, or other means.	\$640.00	2014	Superintendent of Schools	
148	Chamberlain Elementary School	14-022	E. Service Counter	2' downward approach - surface <0°' long	Priority 4	Access to Goods and Services	Modify counters on each office with public interface so that they are accessible. In the meantime, provide an auxiliary counter no higher than 36" above the floor in close proximity to the main counter, or provide equivalent facilitation. Equivalent facilitation may be provided in the form of a folding shelf attached to the main counter, an auxiliary table nearby, a clipboard made available to the public, or other means.	\$640.00	2014	Superintendent of Schools	
149	Chamberlain Elementary School	14-081	E. Service Counter		Priority 4	Access to Goods and Services	Modify counters on each office with public interface so that they are accessible. In the meantime, provide an auxiliary counter no higher than 36" above the floor in close proximity to the main counter, or provide equivalent facilitation. Equivalent facilitation may be provided in the form of a folding shelf attached to the main counter, an auxiliary table nearby, a clipboard made available to the public, or other means.	\$640.00	2014	Superintendent of Schools	
150	Chamberlain Elementary School	14-075	F. Dining or Work Surface	A: number of tables provided B: number of accessible tables provided C: not more than 1% accessible not provided D: floor space not provided E: knee clearance at tables not provided	art room	Priority 4	Access to Goods and Services	Provide 1 accessible, adjustable seat.	\$300.00	2014	Superintendent of Schools
151	Chamberlain Elementary School	14-031, 14-031	F. Dining or Work Surface	A: number of tables provided B: floor clearance at tables not provided C: floor of dining surface <28" or >34"	Guidance office	Priority 4	Access to Goods and Services	Provide a table that is 34" high at the end, and maintain a 36" clear space around the table. Provide rectangular computer table with adequate knee clearance. Provide 1 curved group computer table with	\$500.00	2014	Superintendent of Schools
152	Chamberlain Elementary School	14-027, 14-028	F. Dining or Work Surface	A: number of tables provided B: floor clearance at tables not provided C: floor of dining surface <28" or >34"	Library	Priority 4	Access to Goods and Services	Lower one side so that the rim or counter is 28-31" above the finish floor with adequate knee clearance.	\$1,000.00	2012	Superintendent of Schools
153	Chamberlain Elementary School	14-074	F. Dining or Work Surface	C: floor of dining surface <28" or >34"	2nd Fl Media Arts room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$1,370.00	2014	Superintendent of Schools
154	Chamberlain Elementary School	14-080	J. Storage	Not provided: 216.2	Guidance office 1st floor	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
155	Chamberlain Elementary School	14-025	J. Storage	A: not provided: 216.4	Library	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
156	Chamberlain Elementary School	14-088	J. Storage	A: not provided: 216.3	Main Office	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$350.00	2014	Superintendent of Schools
157	Chamberlain Elementary School	14-096, 14-087	J. Storage	A: not provided: 216.2		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
158	Chamberlain Elementary School	14-090	J. Storage	A: not provided: 216.2		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
159	Chamberlain Elementary School	14-044	J. Storage	A: not provided: 216.4.3		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
160	Chamberlain Elementary School	14-080	J. Storage	A: not provided at steps: 216.3		Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
161	Chamberlain Elementary School	14-021	J. Storage	B: not provided: 216.2	Library	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2014	Superintendent of Schools
162	Chamberlain Elementary School	14-037	J. Storage	B: not provided: 216.2	Main entrance	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2014	Superintendent of Schools
163	Chamberlain Elementary School	14-042	J. Storage	B: not provided: 216.2		Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2014	Superintendent of Schools
164	Chamberlain Elementary School	14-071	J. Storage	B: not provided: 216.2	Sub-separate 3rd grade 2nd fl	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2014	Superintendent of Schools
165	Chamberlain Elementary School	14-016	J. Storage	B: not provided: 216.2	Nurse's station	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
166	Chamberlain Elementary School	14-030	J. Storage	C: not provided, non-compliant	Guidance Suite	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
167	Chamberlain Elementary School	14-034	J. Storage	no permanent room signage: 216.2	Guidance Office entrance Suite	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
168	Chamberlain Elementary School	14-073	J. Storage	Programs not identified: 703.6.3 Program Field. Programs shall have a field height of 4 inches (10 cm) minimum. Characters and braille that shall be located in the program field. 703.6.3 Text Descriptions. Programs shall have text descriptions located directly below the program field. Text descriptions shall comply with 703.2, 703.3 and 703.4	Tools & Materials Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
169	Chamberlain Elementary School	14-072	J. Storage	signage on both side should be Emergency Egress Route signage in back of teacher's desk should identify door as leading to Girl's Toilet Room	classroom on other side of girl's entrance toilet stall	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
170	Chamberlain Elementary School	14-037	J. Storage	signage too high where placed, and non-existent otherwise 216.2	PAF	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
171	Chamberlain Elementary School	14-055	K. Entry	A: not provided: 216.2	Toilet Room	Priority 5	Toilet or Bathing Rooms	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2014	Superintendent of Schools
172	Chamberlain Elementary School	14-060	K. Overall Access	C: accessible Accessories not provided	signaled accessible toilet	Priority 5	Toilet or Bathing Rooms	Lower coat hook to 48" above finish floor.	\$50.00	2014	Superintendent of Schools
173	Chamberlain Elementary School	14-061	K. Overall Access	C: accessible Accessories not provided	signaled ambulatory toilet	Priority 5	Toilet or Bathing Rooms	Lower coat hook to 48" above finish floor.	\$50.00	2014	Superintendent of Schools
174	Chamberlain Elementary School	14-057	K. Lavatory	A: floor space not provided at lavatory B: floor or knee clearance not provided C: rim or counter >34"	1st grades 1,2 and 3	Priority 5	Toilet or Bathing Rooms	Install lavatory with a knee clearance of 24" above the finish floor and a counter of 33" for one girl's and one boy's room.	\$6,000.00	2014	Superintendent of Schools
175	Chamberlain Elementary School	14-053	K. Lavatory	C: rim or counter >34" B: floor above lavatory w/ reflective surface > 40"	typical lavatory	Priority 5	Toilet or Bathing Rooms	For all other boys and girl's rooms, provide a ramp directing children to the accessible lavatory.	\$150 per restroom	2014	Superintendent of Schools
176	Chamberlain Elementary School	14-058	K. Toilet	C: rim or counter >34"	typical accessible toilet	Priority 5	Toilet or Bathing Rooms	Install coat hook and bars at 36"	\$400.00	2014	Superintendent of Schools
177	Chamberlain Elementary School	14-054	T. Toilet Compartment	Door with non-compliant hardware, door with malfunctioning self-closing hinge, coat hook at 53", signage	girls accessible stall	Priority 5	Toilet or Bathing Rooms	Install compliant hardware, repair self-closing hinge, lower coat hook to 48" and install stress signage	\$500.00	2014	Superintendent of Schools
178	Chamberlain Elementary School	14-091	A. Drinking Fountain	A: floor space not provided at drinking fountain		Priority 6	Additional Access	Install 3 drinking fountains with knee and toe clearance.	\$1,200.00	2014	Superintendent of Schools
179	Chamberlain Elementary School	14-050	B. Sink	A: floor space not provided at sink B: floor or knee clearance not provided D: compliant faucets	reading room Grades 1 & 2	Priority 6	Additional Access	Provide 1 accessible classroom for each type of classroom and primarily for children 6-12, where the rim or counter is between 28-31" compliant faucets are provided, clear floor space is provided and the knee clearance is provided.	\$3,000 per classroom	2014	Superintendent of Schools
180	Chamberlain Elementary School	14-067	F. Clothes Rod / Hooks	A: floor space not provided B: rods, > 40"	2nd floor 3rd Grades class	Priority 6	Additional Access	Lower hooks and provide storage 40" above the floor for children 5-8, and 44" above the floor for children 9-12		2014	Superintendent of Schools
181	Chamberlain Elementary School	14-092		near Play area - BB cut		Priority 6	Additional Access	Provide an accessible route to playground.		2014	Superintendent of Schools
182	Chamberlain Elementary School	14-093		near playground		Priority 6	Additional Access	Provide accessible ramped surface.		2014	Superintendent of Schools
183	Chamberlain Elementary School	14-093		West Playground		Priority 6	Additional Access	Provide accessible route connecting all components.		2014	Superintendent of Schools
184	Chamberlain Elementary School	14-086		South playground		Priority 6	Additional Access	Provide an accessible route to playground.		2014	Superintendent of Schools
185	Cohasset School	14-019	B. Curb Ramp	D: does not prevent accumulation of water. D. Not in operable position condition.		Priority 3	Approach and Entrance	Ensure curb ramps are maintained in good condition.	\$400.00	2014	Superintendent of Schools
186	Cohasset School	14-024	D. Off-Street Parking Spaces	Not in operable working condition B: number of spaces not provided D: space not operable		Priority 3	Approach and Entrance	Provide 1 accessible and 1 van accessible space.	\$1,740.00	2014	Superintendent of Schools
187	Cohasset School	14-015	D. Walkway (in a building)	Not maintained in operable working condition		Priority 3	Approach and Entrance	Repair stairs.	\$400.00	2014	Superintendent of Schools
188	Cohasset School	14-017, 14-018, 14-014, 14-013	E. Entrance	Not safe, firm, and slip resistant		Priority 3	Approach and Entrance	Secure all weather mats with industrial strength double stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2014	Superintendent of Schools
189	Cohasset School	14-018	Passenger Loading Zone	Not in operable working condition		Priority 3	Approach and Entrance	Clearly mark drop off area in front of the accessible entrance.	\$400.00	2014	Superintendent of Schools
190	Cohasset School	14-020	Restroom	Not in operable working condition	Restroom, Room	Priority 3	Approach and Entrance	Access to Goods and Services	\$500.00	2014	Superintendent of Schools

4	Cohasset School	104-001			A. Door	J.Boor closed reaches 12 degrees in < 5 seconds	Boys Toilet Room	Priority 4	Access to Goods and Services	Adjust closers so that door closes reaches 12 degrees in 5 seconds or more. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2016	Mar-16	Superintendent of Schools	completed	
5	Cohasset School	104-009			A. Door	K.Boor requires < 5 pounds of force to open	Girls Toilet Room	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2016	Mar-16	Superintendent of Schools	completed	
6	Cohasset School	104-005			A. Door	N.Broom light located < 4'3" AFT		Priority 4	Access to Goods and Services	When replacing door, select a door with a 4'3" clearance.				Superintendent of Schools		
7	Cohasset School	104-002			I. Signage	E. Missing or non-compliant ISA	Boys Toilet Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00	2016	Mar-16	Superintendent of Schools	completed	
8	Cohasset School	104-010			I. Signage	F. Missing or non-compliant ISA	Girls Toilet Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00			Superintendent of Schools		
9	Cohasset School	104-011			I. Signage	F. Missing or non-compliant ISA	Boys Toilet Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00			Superintendent of Schools		
10	E. Pole Elementary School	10-002			D. Interior Route	A.Barrier not securely attached	vestibule (004)	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
11	E. Pole Elementary School	10-003			D. Interior Route	A.Barrier not securely attached	lobby (004)	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
12	E. Pole Elementary School	10-006			D. Interior Route	A.Barrier not securely attached	vestibule (005)	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
13	E. Pole Elementary School	10-008			D. Interior Route	A.Barrier not securely attached	lobby (005)	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
14	E. Pole Elementary School	10-010			D. Interior Route	A.Barrier not securely attached	stair 1 (004)	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
15	E. Pole Elementary School	10-014, 10-015			H. Lift	A.Bolt in operable working condition B.Bolt independently operable	Cafeteria	Priority 4	Access to Goods and Services	Ensure there is a clear route to the lift, provide signage, and install an audible and visible two-way communication system.	\$2,200.00			Superintendent of Schools		
16	E. Pole Elementary School	10-004			I. Signage	B.Broaded, misplaced	administration (001)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door. Ensure that the bottom edge of the tactile characters are between 48" or 60" above the finish floor.	\$50.00	2016		Superintendent of Schools		
17	E. Pole Elementary School	10-005			I. Signage	B.Broaded, misplaced	office (003)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door. Ensure that the bottom edge of the tactile characters are between 48" or 60" above the finish floor.	\$50.00	2016		Superintendent of Schools		
18	E. Pole Elementary School	10-009			I. Signage	B.Broaded, misplaced	stair 1	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door. Ensure that the bottom edge of the tactile characters are between 48" or 60" above the finish floor.	\$50.00	2016		Superintendent of Schools		
19	E. Pole Elementary School	10-011			I. Signage	B.Broaded, misplaced	corridor	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door. Ensure that the bottom edge of the tactile characters are between 48" or 60" above the finish floor.	\$50.00	2016		Superintendent of Schools		
20	E. Pole Elementary School	10-012			I. Signage	B.Broaded, misplaced	electrical closet	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door. Ensure that the bottom edge of the tactile characters are between 48" or 60" above the finish floor.	\$50.00	2016		Superintendent of Schools		
21	E. Pole Elementary School	10-013			I. Signage	B.Broaded, misplaced	classroom typical	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door. Ensure that the bottom edge of the tactile characters are between 48" or 60" above the finish floor.	\$50.00	2016		Superintendent of Schools		
22	E. Pole Elementary School	10-007			G. Electrical and Environmental Controls	E.Border reach over an obstruction < 20" wide x > 48" high	entrance (004)	Priority 6	Additional Access	When renovations occur, lower environmental controls to 48" above the ground.	\$450.00			Superintendent of Schools		
23	E. Pole Elementary School	10-001			G. Electrical and Environmental Controls	E.Border reach over an obstruction < 20" wide x > 48" high	entrance (005)	Priority 6	Additional Access	When renovations occur, lower environmental controls to 48" above the ground.	\$450.00			Superintendent of Schools		
24	East Taunton Elementary School	100-003			B. Curb Ramp	Q.Bolt in operable working condition		Priority 3	Approach and Entrance	Patch bottom of curb ramp to prevent accumulation of water.	\$80.00			Superintendent of Schools		
25	East Taunton Elementary School	100-007			D. Off-Street Parking Spaces	A.Bolt #4 if parking spaces 40 ft or less		Priority 3	Approach and Entrance	Provide 3 van-accessible and 1 accessible space with an access aisle.	\$1,740.00	2016		Superintendent of Schools		
26	East Taunton Elementary School	100-008			D. Off-Street Parking Spaces	A.Bolt #4 if parking spaces 23 ft or less		Priority 3	Approach and Entrance	Adequate number of spaces in this lot.	\$0.00	2016		Superintendent of Schools		
27	East Taunton Elementary School	100-008			D. Off-Street Parking Spaces	A.Bolt #4 if parking spaces 33 ft or less		Priority 3	Approach and Entrance	Adequate number of spaces in this lot.	\$0.00	2016		Superintendent of Schools		
28	East Taunton Elementary School	100-002			D. Off-Street Parking Spaces	M.Bolt #40" above finished floor		Priority 3	Approach and Entrance	Relocate sign to be 60" from ground surface.	\$200.00	2016		Superintendent of Schools		
29	East Taunton Elementary School	100-003			D. Off-Street Parking Spaces	N.Bolt in operable working condition		Priority 3	Approach and Entrance	Repair surface at access aisle.	\$300.00			Superintendent of Schools		
30	East Taunton Elementary School	100-009			D. Off-Street Parking Spaces	N.Bolt in operable working condition		Priority 3	Approach and Entrance	Repair surface at access aisle and access to the building.	\$300.00			Superintendent of Schools		
31	East Taunton Elementary School	100-000			E. Gate	K.Bolt smooth surface not provided at bottom 10"		Priority 3	Approach and Entrance	Provide a smooth surface on the push side of the gate.	\$100.00	2016	Feb-16	Superintendent of Schools	completed	
32	East Taunton Elementary School	100-005			H. Entrance	H.Surface not stable, firm, and slip-resistant	lobby	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
33	East Taunton Elementary School	100-016			H. Entrance	H.Surface not stable, firm, and slip-resistant	lobby	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
34	East Taunton Elementary School	100-006			H. Entrance			Priority 3	Approach and Entrance	Provide an audible and visual two-way communication system at secondary entrance.	\$2,000.00			Superintendent of Schools		
35	East Taunton Elementary School	100-001			H. Entrance			Priority 3	Approach and Entrance	Provide an accessible route to classroom.				Superintendent of Schools		
36	East Taunton Elementary School	100-011			A. Door	C.Bolt (narrowing clearance) not provided	teacher's room	Priority 4	Access to Goods and Services	Move furniture to provide unobstructed clearance.	\$50.00	2016	Feb-16	Superintendent of Schools	completed	
37	East Taunton Elementary School	100-019			A. Door	C.Bolt (narrowing clearance) not provided	OT room	Priority 4	Access to Goods and Services	Move furniture to provide unobstructed clearance.	\$50.00	2016	Feb-16	Superintendent of Schools	completed	
38	East Taunton Elementary School	100-041			A. Door	C.Bolt (narrowing clearance) not provided	computer room	Priority 4	Access to Goods and Services	Move furniture to provide unobstructed clearance.	\$50.00	2016	Feb-16	Superintendent of Schools	completed	
39	East Taunton Elementary School	100-043			A. Door	F.Bolt requires < 5 pounds of force to open	computer room	Priority 4	Access to Goods and Services	Adjust door opening device.	\$100.00	2016	Feb-16	Superintendent of Schools	completed	
40	East Taunton Elementary School	100-043 b			A. Door	F.Bolt requires < 5 pounds of force to open	computer room	Priority 4	Access to Goods and Services	Adjust door opening device.	\$100.00	2016	Feb-16	Superintendent of Schools	completed	
41	East Taunton Elementary School	100-045			B. Stairway (interior)	B.Railings have non-compliant cross section B.Railings do not extend 12" from stairs		Priority 4	Access to Goods and Services	Install handrails to comply with requirements occur, replace handrail. 2 sets of stairs to check.	\$1,080.00			Superintendent of Schools		
42	East Taunton Elementary School	100-044			D. Interior Route	D.Bolts obstruct by protruding objects	corridor	Priority 2	Safety	Remove lock so that it is higher than 80"	\$100.00	2016		Superintendent of Schools		
43	East Taunton Elementary School	100-030			D. Interior Route	D.Surface not stable, firm, and slip-resistant		Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
44	East Taunton Elementary School	100-021			D. Interior Route	D.Surface not stable, firm, and slip-resistant		Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates.	\$200.00	2016	Dec-16	Superintendent of Schools	completed	
45	East Taunton Elementary School	100-035			F. Dining or Work Surface	C.Bolt meet one or 5% accessible not provided	cafeteria	Priority 4	Access to Goods and Services	Provide at least one accessible dining surface. Remove attached seats if possible, or purchase a new table.	\$200.00	2016		Superintendent of Schools		
46	East Taunton Elementary School	100-042			F. Dining or Work Surface	C.Bolt of dining surface: < 28" or > 34"	computer room	Priority 4	Access to Goods and Services	Provide at least 1 or 5% accessible seating with adequate knee clearance to the computer room.	\$500.00	2016		Superintendent of Schools		

132	East Taunton Elementary School	10-037		F. Dining or Work Surface	G.Rise of dining surfaces <28" or >34" A.Number of tables provided B.Minimum one or 5% accessible not provided	library	Priority 4	Access to Goods and Services	Provide at least 1 or 5% circular accessible tables with adequate knee clearance in the library	\$500.00	2016	Superintendent of Schools		
133	East Taunton Elementary School	10-038		F. Dining or Work Surface	G.Rise of dining surfaces <28" or >34" A.Number of tables provided B.Minimum one or 5% accessible not provided	library	Priority 4	Access to Goods and Services	Provide at least 1 or 5% rectangular accessible seating with adequate knee clearance in the library	\$500.00	2016	Superintendent of Schools		
140	East Taunton Elementary School	10-047		H. Lift	B.Not independently operable		Priority 4	Access to Goods and Services	Upgrade lift to be independently operable. Consider replacing lift with a larger lift that is independently operable.	\$1,200.00		Superintendent of Schools		
141	East Taunton Elementary School	10-046		H. Lift	E.30" x 54" clear floor space not provided		Priority 4	Access to Goods and Services	Move stored items to maintain a clear space in lift.	\$50.00	2016	Superintendent of Schools		
135	East Taunton Elementary School	10-036		I. Signage	B.Brochured, misplaced	library	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
142	East Taunton Elementary School	10-006		I. Signage	C.Brochured, non-compliant		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
143	East Taunton Elementary School	10-009		I. Signage	D.Brochured, fixed <6"	corridor room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
144	East Taunton Elementary School	10-015		I. Signage	D.Brochured, fixed <6"		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
145	East Taunton Elementary School	10-008		C. Lavatory	F.Better above lavatory w/ reflective surface > 40"	restroom	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$200.00	2016	Superintendent of Schools		
146	East Taunton Elementary School	10-013		C. Lavatory	F.Better above lavatory w/ reflective surface > 40"	restroom	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$200.00	2016	Superintendent of Schools		
147	East Taunton Elementary School	10-018		C. Lavatory	F.Better above lavatory w/ reflective surface > 40"	unisex toilet room	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$200.00	2016	Superintendent of Schools		
121	East Taunton Elementary School	10-025		C. Lavatory	F.Better above lavatory w/ reflective surface > 40"	unisex toilet room	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$200.00	2016	Superintendent of Schools		
128	East Taunton Elementary School	10-022		D. Toilet	B.Inadequate maneuvering clearances	restroom	Priority 5	Toilet or Bathing Rooms	Remove lockers.	\$50.00	2016	Superintendent of Schools	completed	
129	East Taunton Elementary School	10-017		D. Toilet	B.Inadequate maneuvering clearances	unisex staff toilet room	Priority 5	Toilet or Bathing Rooms	Remove furniture.	\$50.00	2016	Superintendent of Schools	completed	
130	East Taunton Elementary School	10-004		D. Toilet	B.Inadequate maneuvering clearances	restroom	Priority 5	Toilet or Bathing Rooms	Remove lockers.	\$50.00	2016	Superintendent of Schools	completed	
131	East Taunton Elementary School	10-007		A. Table	A.No room for table and chair.	restroom	Priority 5	Toilet or Bathing Rooms	Provide accessible table.	\$300.00		Superintendent of Schools		
148	East Taunton Elementary School	10-033		A. Drinking Fountain	A.Better floor space not provided at drinking fountain	gymnasium	Priority 6	Additional Access	Provide at least one 6" to no drinking fountain.	\$2,000.00		Superintendent of Schools		
149	East Taunton Elementary School	10-010		B. Sink	B.No and three clearances not provided		Priority 6	Additional Access	Replace or move a sink so that it has 12" of clear space underneath.	\$2,211.00		Superintendent of Schools		
150	East Taunton Elementary School	10-039		B. Sink	B.No and three clearances not provided	art room	Priority 6	Additional Access	Replace or move a sink so that it has 12" of clear space underneath.	\$2,211.00		Superintendent of Schools		
297	Friedman Middle School	10-001		D. Interior Route	A.Barrge not securely attached	lobby	Priority 2	Safety	Secure all weather mats with industrial strength double click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Superintendent of Schools	completed	
311	Friedman Middle School	10-015		D. Interior Route	A.Barrge not securely attached	corridor	Priority 2	Safety	Secure all weather mats with industrial strength double click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Superintendent of Schools	completed	
320	Friedman Middle School	10-010		D. Interior Route	A.Barrge not securely attached	cafeteria	Priority 2	Safety	Secure all weather mats with industrial strength double click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Superintendent of Schools	completed	
327	Friedman Middle School	10-011		D. Interior Route	A.Barrge not securely attached	cafeteria	Priority 2	Safety	Secure all weather mats with industrial strength double click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Superintendent of Schools	completed	
328	Friedman Middle School	10-032		D. Interior Route	A.Barrge not securely attached	corridor (303)	Priority 2	Safety	Secure all weather mats with industrial strength double click tops. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Superintendent of Schools	completed	
380	Friedman Middle School	10-005		A. Interior Route	C.Barrge not securely attached	lab (315)	Priority 2	Safety	Relocate and install signs.	\$100.00	2016	Superintendent of Schools	signs done	signs done
381	Friedman Middle School	10-018		D. Interior Route	C.Barrge not securely attached	corridor	Priority 2	Safety	Relocate and install signs.	\$100.00	2016	Superintendent of Schools	signs done	signs done
382	Friedman Middle School	10-038		A. Interior Route	C.Barrge not securely attached	corridor	Priority 2	Safety	Relocate and install signs.	\$100.00	2016	Superintendent of Schools	signs done	signs done
213	Friedman Middle School	10-017		E. Service Counter	B.Better >36" high	library	Priority 4	Access to Goods and Services	Modify counters on each office with public interface so that they are accessible to the maximum, provide an auxiliary counter no higher than 48" above the floor in close proximity to the main counter, or provide equivalent facilitation. Equivalent facilitation may be provided in the form of a folding shelf attached to the main counter, an auxiliary table nearby, a clipboard made available to the public, or other means.	\$640.00	2016	Superintendent of Schools		
327	Friedman Middle School	10-041		F. Dining or Work Surface	A.Number of tables provided B.Number of accessible tables provided C.Minimum one or 5% accessible not provided D.Better floor space not provided	computer room (244)	Priority 4	Access to Goods and Services	Provide 2 accessible tables with adequate clear space.	\$1,000.00	2016	Superintendent of Schools		
343	Friedman Middle School	10-016		I. Signage	A.Better provided	computer room (130)	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
344	Friedman Middle School	10-019		I. Signage	A.Better provided	corridor (322-324)	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
345	Friedman Middle School	10-037		I. Signage	A.Better provided	egress stairway	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
346	Friedman Middle School	10-038		I. Signage	A.Better provided	classroom (226)	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
348	Friedman Middle School	10-002		I. Signage	B.Brochured, misplaced	main office	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
349	Friedman Middle School	10-006		I. Signage	B.Brochured, misplaced	classroom (116A)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
350	Friedman Middle School	10-007		I. Signage	B.Brochured, misplaced	classroom (116B)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
360	Friedman Middle School	10-013		I. Signage	B.Brochured, misplaced	classroom typical	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
361	Friedman Middle School	10-014		I. Signage	B.Brochured, misplaced	library	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
362	Friedman Middle School	10-020		I. Signage	B.Brochured, misplaced	exercise room (324)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
363	Friedman Middle School	10-021		I. Signage	B.Brochured, misplaced	weight room (322)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
364	Friedman Middle School	10-028		I. Signage	B.Brochured, misplaced	music room (311)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
365	Friedman Middle School	10-029		I. Signage	B.Brochured, misplaced	cafeteria	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
366	Friedman Middle School	10-033		I. Signage	B.Brochured, misplaced	nurse	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
367	Friedman Middle School	10-035		I. Signage	B.Brochured, misplaced	family leadership center (108)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
368	Friedman Middle School	10-039		I. Signage	B.Brochured, misplaced	teachers lounge (246)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
369	Friedman Middle School	10-040		I. Signage	B.Brochured, misplaced	computer room (244)	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Superintendent of Schools		
384	Friedman Middle School	10-008		C. Lavatory	F.Better above lavatory w/ reflective surface > 40"	boys' toilet room	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$200.00	2016	Superintendent of Schools		
385	Friedman Middle School	10-009		F. Accessory	A.Barrge > 48" height B.Better floor space not provided at accessory	boys' toilet room	Priority 5	Toilet or Bathing Rooms	Relocate paper towels so that they have a 30" centered clear space and are located between 25" and 48" above the finish floor.	\$100.00	2016	Superintendent of Schools		
386	Friedman Middle School	10-012		F. Accessory	A.Barrge > 48" height B.Better floor space not provided at accessory	girls' toilet room	Priority 5	Toilet or Bathing Rooms	Relocate paper towels so that they have a 30" centered clear space and are located between 25" and 48" above the finish floor.	\$100.00	2016	Superintendent of Schools		
407	Friedman Middle School	10-011		D. Toilet Compartment	C.Better compliant side or rear grab bars D.Better hooks > 48"	girls' toilet room	Priority 5	Toilet or Bathing Rooms	Replace 2 grab bars, repair self-closing hinge, and lower coat hook.	\$750.00	2016	Superintendent of Schools		
396	Friedman Middle School	10-010		D. Toilet Compartment	C.Better compliant side or rear grab bars D.Better hooks > 48"	boys' toilet room	Priority 5	Toilet or Bathing Rooms	Replace 2 grab bars, repair self-closing hinge, and lower coat hook.	\$750.00	2016	Superintendent of Schools		
398	Friedman Middle School	10-022		D. Toilet Compartment	C.Better compliant side or rear grab bars D.Better hooks > 48"	girls' locker room	Priority 5	Toilet or Bathing Rooms	Replace 2 grab bars, repair self-closing hinge, and lower coat hook.	\$750.00	2016	Superintendent of Schools		
399	Friedman Middle School	10-025		D. Toilet Compartment	C.Better compliant side or rear grab bars D.Better hooks > 48"	boys' locker room	Priority 5	Toilet or Bathing Rooms	Replace 2 grab bars, repair self-closing hinge, and lower coat hook.	\$750.00	2016	Superintendent of Schools		
395	Friedman Middle School	10-023		K. Lockers	A.Better floor space not provided B.Better compliant hardware C.Better number of lockers D.Better compliant hardware E.Better number of lockers F.Better compliant hardware	girls' locker room	Priority 4	Access to Goods and Services	Provide 2 accessible lockers with clear floor space and compliant hardware.	\$1,500.00		Superintendent of Schools		
400	Friedman Middle School	10-027		K. Lockers	A.Better floor space not provided B.Better compliant hardware C.Better number of lockers D.Better compliant hardware E.Better number of lockers F.Better compliant hardware	boys' locker room	Priority 4	Access to Goods and Services	Provide 2 accessible lockers with clear floor space and compliant hardware.	\$1,500.00		Superintendent of Schools		
403	Friedman Middle School	10-004		G. Electrical and Environmental Controls	B.Better reach over an obstruction <20" w/dia > 48" high	lab (315)	Priority 6	Additional Access	Lower paper towels so that control is no higher than 48" above the finish floor.	\$100.00		Superintendent of Schools		
399	Friedman Middle School	10-003		M. Storage	B.Better storage operable parts > 48" height	corridor	Priority 6	Additional Access	Provide 2 accessible lockers with clear floor space and compliant hardware.	\$1,500.00		Superintendent of Schools		

122	Friedman Middle School	IS-036		M. Storage	C)Storage hardware not compliant	corridor	Priority 6	Additional Access	Provide 2 accessible lockers with clear floor space and compliant hardware.	\$1,500.00			Superintendent of Schools		
128	Galigan Elementary School	IS-000		A. Pedestrian Street Crossing	C)Inadequate drainage		Priority 3	Approach and Entrance	Repair curb ramp so that water does not pool.	\$1,635.00			Superintendent of Schools		
129	Galigan Elementary School	IS-023		A. Pedestrian Street Crossing	I)Not in operable working condition		Priority 3	Approach and Entrance	Repair asphalt street crossing.	\$320.00			Superintendent of Schools		
129	Galigan Elementary School	IS-040		C. Accessible Route/Walkway	F)Surface not stable, firm, and slip-resistant		Priority 2	Safety	Secure all weather mats with industrial-strength double-clip tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2019	Dec-19	Superintendent of Schools	completed	
165	Galigan Elementary School	IS-027		C. Accessible Route/Walkway	H)Cross slope >1:48		Priority 3	Approach and Entrance	Repair asphalt sidewalk.	\$1,800.00			Superintendent of Schools		
167	Galigan Elementary School	IS-033		C. Accessible Route/Walkway	I)Not in operable working condition		Priority 3	Approach and Entrance	Patch asphalt playground.	\$180.00			Superintendent of Schools		
169	Galigan Elementary School	IS-036		C. Accessible Route/Walkway	I)Not in operable working condition		Priority 3	Approach and Entrance	Patch asphalt playground.	\$288.00			Superintendent of Schools		
180	Galigan Elementary School	IS-026		C. Accessible Route/Walkway	I)Not in operable working condition		Priority 3	Approach and Entrance	Repair asphalt street crossing.	\$320.00			Superintendent of Schools		
180	Galigan Elementary School	IS-035		F. Gate	L)Not in operable working condition		Priority 3	Approach and Entrance	Provide a smooth surface on the push side of the gate and repair gate.	\$200.00			Feb-19	Superintendent of Schools	completed
182	Galigan Elementary School	IS-035		F. Gate (in a Walkway)	L)Smooth surface not provided at bottom 10"		Priority 3	Approach and Entrance	Repair concrete.	\$600.00			Superintendent of Schools		
182	Galigan Elementary School	IS-035		F. Gate (in a Walkway)	L)Smooth surface not provided at bottom 10"		Priority 3	Approach and Entrance	Repair concrete.	\$119.45			Superintendent of Schools		
182	Galigan Elementary School	IS-030		F. Ramp (in a Walkway)	C)Handrail has changes in level >1/4"		Priority 3	Approach and Entrance	Make minor repairs to address changes in level.	\$300.00			Superintendent of Schools		
182	Galigan Elementary School	IS-028		G. Stairway (in a Walkway)	F)Handrails not continuous where required		Priority 3	Approach and Entrance	Provide new handrail on 1 side of stair. Add handrail extension to the top and bottom of the other side.	\$2,300.00			Superintendent of Schools		
182	Galigan Elementary School	IS-034		H. Entrance	I)If not Accessible - Directional Sign not Provided		Priority 3	Approach and Entrance	Provide a directional sign to the accessible entrance.	\$260.00	2019		Superintendent of Schools		
184	Galigan Elementary School	IS-032		H. Entrance	L)Threshold >1/2" high		Priority 3	Approach and Entrance	Reduce threshold.	\$350.00			Superintendent of Schools		
184	Galigan Elementary School	IS-070		H. Entrance	L)Threshold >1/2" high		Priority 3	Approach and Entrance	Provide a directional sign to access the entrance.	\$260.00			Superintendent of Schools		
191	Galigan Elementary School	IS-062		A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Move furniture and other items to maintain maneuvering clearance.	\$50.00	2019		Superintendent of Schools		
191	Galigan Elementary School	IS-046		A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Move furniture and other items to maintain maneuvering clearance.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-043		A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Move furniture and other items to maintain maneuvering clearance.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-044		A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Move furniture and other items to maintain maneuvering clearance.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-045		A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Move furniture and other items to maintain maneuvering clearance.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-042		A. Door	C)Maneuvering clearance(s) not provided	girls toilet room	Priority 4	Access to Goods and Services	Move furniture and other items to maintain maneuvering clearance.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-050		A. Door	C)Maneuvering clearance(s) not provided	cafeteria	Priority 4	Access to Goods and Services	2 exit doors in cafeteria have the same issues. They require 32" clear on push side. Adjust closers and provide smooth surfaces on both doors. Install an automatic door opener on one door and provide signage to the accessible exit on the other door.	\$2,060.00			Superintendent of Schools		
191	Galigan Elementary School	IS-005a		A. Door	C)Maneuvering clearance(s) not provided	offices	Priority 4	Access to Goods and Services	Move furniture and other items.	\$200.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-005b		A. Door	K)Door requires >5 pounds of force to open	offices	Priority 4	Access to Goods and Services	Adjust closers for 3 doors. In the future consider replacing doors with doors with compliant vision panels.	\$200.00	2019		Superintendent of Schools		
191	Galigan Elementary School	IS-055a		A. Door	M)Smooth surface not provided at bottom 10"	kindergarten bathroom	Priority 4	Access to Goods and Services	provide a 10" smooth surface on the push side.	\$150.00	2019		Superintendent of Schools		
191	Galigan Elementary School	IS-055b		A. Door	C)Maneuvering clearance(s) not provided	kindergarten bathroom	Priority 4	Access to Goods and Services	Move furniture to provide maneuvering clearance.	\$150.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-006		A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Move furniture and other items.	\$400.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-004		A. Door	B)Barriers inoperable		Priority 4	Access to Goods and Services	Install compliant door hardware.	\$440.00			Superintendent of Schools		
191	Galigan Elementary School	IS-017		A. Door	K)Door requires >5 pounds of force to open		Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2019	Jan-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-048		A. Door	K)Door requires >5 pounds of force to open		Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2019	Jan-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-006		A. Door	K)Door requires >5 pounds of force to open		Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener. Provide a 10" smooth surface on the push side.	\$150.00	2019	Jan-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-023		A. Door	K)Door requires >5 pounds of force to open	library	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$495.00	2019	Jan-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-059		B. Stairway (interior)	B)Risks <11" deep	cafeteria	Priority 4	Access to Goods and Services	Install 12" handrail extensions for 3 sets of stairs. If cafeteria is renovated consider re-installing stairs with compliant risers and treads.	\$576.00			Superintendent of Schools		
191	Galigan Elementary School	IS-067		B. Stairway (interior)	L)Handrails do not extend 12" from stairs	cafeteria	Priority 4	Access to Goods and Services	Install 12" extensions at top and bottom.	\$288.00			Superintendent of Schools		
191	Galigan Elementary School	IS-068		B. Stairway (interior)	L)Handrails do not extend 12" from stairs	cafeteria	Priority 4	Access to Goods and Services	Install 12" extensions at top and bottom.	\$388.00			Superintendent of Schools		
191	Galigan Elementary School	IS-022		D. Interior Route	D)Surface not stable, firm, and slip-resistant	library	Priority 2	Safety	Secure all weather mats with industrial-strength double-clip tape.	\$200.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-041		D. Interior Route	D)Surface not stable, firm, and slip-resistant		Priority 2	Safety	Secure all weather mats with industrial-strength double-clip tape.	\$200.00	2019	Dec-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-058		D. Interior Route	E)Door width <36"		Priority 4	Access to Goods and Services	Move furniture to maintain a 36" wide clear route.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-009		D. Interior Route	E)Door width <36"		Priority 4	Access to Goods and Services	Move furniture to maintain a 36" wide clear route.	\$50.00	2019	Feb-19	Superintendent of Schools	completed	
191	Galigan Elementary School	IS-009		F. Dining or Work Surface	F)Clear or knee clearance at tables not provided		Priority 4	Access to Goods and Services	Provide 1 table that has 27" clear underneath.	\$500.00	2019		Superintendent of Schools		
191	Galigan Elementary School	IS-053		G. Elevator	F)Audible and visible indicators not provided	cafeteria	Priority 4	Access to Goods and Services	Adjust audible indicator to be louder.	\$150.00			Superintendent of Schools		
191	Galigan Elementary School	IS-012		J. Signage	A)Not provided	boys toilet room	Priority 4	Access to Goods and Services	Install a directional sign directing people to the accessible toilet room, until this toilet room is renovated.	\$150.00			Superintendent of Schools		
191	Galigan Elementary School	IS-063		J. Signage	A)Not provided	girls toilet room	Priority 4	Access to Goods and Services	Install a directional sign directing people to the accessible toilet room, until this toilet room is renovated.	\$300.00			Superintendent of Schools		
191	Galigan Elementary School	IS-066		J. Signage	A)Not provided	boys toilet room	Priority 4	Access to Goods and Services	Install a directional sign directing people to the accessible toilet room, until this toilet room is renovated.	\$150.00			Superintendent of Schools		
191	Galigan Elementary School	IS-069		J. Signage	A)Not provided	cafeteria	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the back side of the door.	\$150.00			Superintendent of Schools		
191	Galigan Elementary School	IS-001		J. Signage	A)Not provided, reconfigured		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the back side of the door.	\$150.00			Superintendent of Schools		



78	High School	56-013	FD-7540	A. Door	K.Boor requires +5 pounds of force to open	boys toilet room	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018	Fid-HS	Superintendent of Schools	completed	
79	High School	56-130	FD-7541	A. Door	K.Boor requires +5 pounds of force to open	girls toilet room	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.		2018	Fid-HS	Superintendent of Schools	completed	
80	High School	56-017	FD-7542	A. Door	K.Boor requires +5 pounds of force to open	girls toilet room	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018	Fid-HS	Superintendent of Schools	completed	
	High School	56-028	No record number in report	A. Door	K.Boor requires +5 pounds of force to open		Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018		Superintendent of Schools		
108	High School	56-125	FD-7544	A. Door	K.Boor requires +5 pounds of force to open	G001	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018	Fid-HS	Superintendent of Schools	completed	
81	High School	56-120	FD-7545	A. Door	K.Boor requires +5 pounds of force to open	auditorium	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018	Fid-HS	Superintendent of Schools	completed	
88	High School	46-093	FD-7546	A. Door	K.Boor requires +5 pounds of force to open	a315	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.		2018	Fid-HS	Superintendent of Schools	completed	
17	High School	tg-101	FD-7547	A. Door	K.Boor requires +5 pounds of force to open	TV video	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018	Fid-HS	Superintendent of Schools	completed	
87	High School	56-115	FD-7548	A. Door	K.Boor requires +5 pounds of force to open	field house	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door opener.	\$50.00	2018	Fid-HS	Superintendent of Schools	completed	
106	High School	56-073		A. Door	M.Bsmooth surface not provided at bottom 10"	child care	Priority 4	Access to Goods and Services	Provide a smooth surface on the push side of the door.	\$100.00			Superintendent of Schools		
83	High School	56-081		A. Door	M.Bsmooth surface not provided at bottom 10"		Priority 4	Access to Goods and Services	Provide a smooth surface on the push side of the door.	\$100.00			Superintendent of Schools		
82	High School	56-091		A. Door	M.Bsmooth surface not provided at bottom 10"		Priority 4	Access to Goods and Services	Provide a smooth surface on the push side of the door.	\$100.00			Superintendent of Schools		
89	High School	56-105		A. Door	M.Bsmooth surface not provided at bottom 10"	math	Priority 4	Access to Goods and Services	Provide a smooth surface on the push side of the door.	\$100.00			Superintendent of Schools		
92	High School	56-003		C. Ramp (interior)	B.Burning slope +1:12	lobby	Priority 4	Access to Goods and Services	When renovations occur, correct the slope of the two 5 shaped ramps in this area.	\$4,000.00			Superintendent of Schools		
90	High School	56-002	FD 7015	D. Interior Route	A.Barrier not securely attached	stair 1A	Priority 2	Safety	Secure all weather mats with industrial strength double click tape. Alternatively, replace them with increased walk-off mats or grates at all entrances.	\$200.00	2018	Fid-HS	Superintendent of Schools	completed	
96	High School	56-124		D. Interior Route	CFS between each type of machine not provided	weight room	Priority 4	Access to Goods and Services	Allow equipment to provide clear space between machines.		2018		Superintendent of Schools		
98	High School	56-083		D. Interior Route	A.Barrier not securely attached	Algo a208	Priority 2	Safety	Secure all weather mats with industrial strength double click tape. Alternatively, replace them with increased walk-off mats or grates at all entrances.	\$200.00	2018	Fid-HS	Superintendent of Schools	completed	
103	High School	56-123		D. Interior Route	A.Barrier not securely attached	weigh room	Priority 2	Safety	Secure all weather mats with industrial strength double click tape. Alternatively, replace them with increased walk-off mats or grates at all entrances.	\$200.00	2018	Fid-HS	Superintendent of Schools	completed	
127	High School	56-009		D. Interior Route	C.Bstructured by protruding objects	lobby	Priority 2	Safety	Relocate protruding object or install a cane detectable barrier under it.	\$100.00	2018		Superintendent of Schools		
84	High School	56-004		D. Interior Route	C.Bstructured by protruding objects	lobby	Priority 2	Safety	Relocate protruding object or install a cane detectable barrier under it.	\$100.00	2018		Superintendent of Schools		
71	High School	56-008		D. Interior Route	C.Bstructured by protruding objects	lobby	Priority 2	Safety	Relocate protruding object or install a cane detectable barrier under it.	\$100.00	2018		Superintendent of Schools		
109	High School	56-075		D. Interior Route	C.Bstructured by protruding objects	a209a	Priority 2	Safety	Relocate dispenser.	\$100.00	2018		Superintendent of Schools		
94	High School	56-050		D. Interior Route	C.Bstructured by protruding objects	a113	Priority 2	Safety	Relocate dispenser.	\$100.00	2018		Superintendent of Schools		
93	High School	56-051		D. Interior Route	C.Bstructured by protruding objects	a114	Priority 2	Safety	Relocate protruding object or install a cane detectable barrier under it.	\$100.00	2018		Superintendent of Schools		
105	High School	56-041		D. Interior Route	C.Bstructured by protruding objects	b218	Priority 2	Safety	Relocate dispenser.	\$100.00	2018		Superintendent of Schools		
130	High School	56-114		D. Interior Route	B.Burning slope +1:12	field house	Priority 4	Access to Goods and Services	Slope at 4 doors exceeds 1:48 and must be corrected when renovation occurs. For now provide signage to accessible entry and correct the excessive amount of force required to open the doors.	\$1,050.00			Superintendent of Schools		
121	High School	56-035		D. Interior Route	E.Bdoor width <36"		Priority 4	Access to Goods and Services	When renovations occur, provide 36" or both side rails in lobby.	780			Superintendent of Schools		
70	High School	56-27		D. Interior Route	E.Bdoor width <36"	brillig	Priority 4	Access to Goods and Services	Allow furniture to maintain a 36" wide clear route throughout and a clear route to the research station.	\$50.00	2018		Superintendent of Schools		
100	High School	56-049	F. Dining or Work Surface	G.Blow knee clearance at tables not provided		b101	Priority 4	Access to Goods and Services	Provide 1 accessible work table.	\$500.00	2018		Superintendent of Schools		
97	High School	56-033		F. Dining or Work Surface	G.Blow knee clearance at tables not provided	b212	Priority 4	Access to Goods and Services	Provide 1 accessible work table.	\$500.00	2018		Superintendent of Schools		
85	High School	56-003		F. Dining or Work Surface	J.Blow knee clearance at tables not provided	balloon	Priority 4	Access to Goods and Services	Provide 2 accessible work table.	\$500.00	2018		Superintendent of Schools		
95	High School	56-038		F. Dining or Work Surface	J.Blow knee clearance at tables not provided	d1w	Priority 4	Access to Goods and Services	Provide 1 accessible work table.	\$500.00	2018		Superintendent of Schools		
91	High School	56-023		F. Dining or Work Surface	G.Blow of dining surfaces <28" or >34"	b103	Priority 4	Access to Goods and Services	Provide 1 accessible work table.	\$500.00	2018		Superintendent of Schools		
99	High School	56-064		F. Dining or Work Surface	G.Blow of dining surfaces <28" or >34"	balloon	Priority 4	Access to Goods and Services	Provide 1 accessible work table.	\$500.00	2018		Superintendent of Schools		
101	High School	56-047		F. Dining or Work Surface	G.Blow of dining surfaces <28" or >34"	m001	Priority 4	Access to Goods and Services	Provide accessible route to picnic table.	\$264.00			Superintendent of Schools		
102	High School	56-112		F. Dining or Work Surface	J.Blow of dining surfaces <28" or >34"	calculus	Priority 4	Access to Goods and Services	Provide 1 accessible work table.	\$500.00			Superintendent of Schools		
96	High School	56-117		H. Lift	B.Mat independently operable	auditorium	Priority 4	Access to Goods and Services	Install control so that lift can be independently operable.	\$1,200.00			Superintendent of Schools		
76	High School	56-138		I. Assembly Area	D.Bsupervisors not provided	auditorium	Priority 4	Access to Goods and Services	When renovations occur, display accessible sign.	780			Superintendent of Schools		
111	High School	56-097		J. Signage	A.Mat provided	a118	Priority 4	Access to Goods and Services	Install an ADA-compliant directional sign directing people to the accessible toilet room.	\$150.00			Superintendent of Schools		
107	High School	56-092		J. Signage	A.Mat provided	a216	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00			Superintendent of Schools		
86	High School	56-113		J. Signage	A.Mat provided	1st fl d	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00			Superintendent of Schools		
	High School	56-045		J. Signage	A.Mat provided	library	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00			Superintendent of Schools		
	High School	56-048		J. Signage	C.Browled, non-compliant		Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2018		Superintendent of Schools		



	High School	56-581			1. Signage	C)Provided, non-compliant		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
	High School	56-100			1. Signage			Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
88	High School	56-044			1. Signage	A)Not provided	3335	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
89	High School	56-015			1. Signage	A)Not provided	8325	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
100	High School	56-012			1. Signage	B)Provided, misplaced	boys toilet room	Priority 4	Access to Goods and Services	Install an ADA-compliant directional sign directing people to the accessible toilet room	\$50.00		Superintendent of Schools		
20	High School	56-037			1. Signage	B)Provided, misplaced	headmaster 3201	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
31	High School	56-046			1. Signage	B)Provided, misplaced	library	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
48	High School	56-085			1. Signage	B)Provided, misplaced	a201	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
50	High School	56-099			1. Signage	B)Provided, misplaced	photo	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
62	High School	56-005			1. Signage	B)Provided, misplaced	level 1	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
100	High School	56-007			1. Signage	C)Provided, non-compliant		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
102	High School	56-011			1. Signage	C)Provided, non-compliant	B house	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
104	High School	56-053			1. Signage	C)Provided, non-compliant	a234	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
105	High School	56-038			1. Signage	C)Provided, non-compliant	3215	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
110	High School	56-039			1. Signage	C)Provided, non-compliant	8235	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
116	High School	56-108			1. Signage	C)Provided, non-compliant	8240	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
118	High School	56-089			1. Signage	D)Braille characters < 48" or > 60" above ground	8425	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$50.00		Superintendent of Schools		
119	High School	56-137			1. Signage	D)Braille characters < 48" or > 60" above ground	boys' locker room	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00		Superintendent of Schools		
18	High School	56-084			1. Signage	F)Enterline > 60" above ground	conference room	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
38	High School	56-127			1. Signage	F)Enterline > 60" above ground	girls' locker room	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door	\$50.00	2019	Superintendent of Schools		
100	High School	56-082			1. Signage	F)Enterline > 60" above ground	a233	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
110	High School	56-126			1. Signage	misplaced. Sign is 37" away from door	G201	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
101	High School	56-043			1. Signage	C. Provided, non-compliant	3316	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00		Superintendent of Schools		
101	High School	56-076			B. Overall Access	B.)Accessible plumbing fixtures or stalls not provided	boys	Priority 5	Toilet or Bathing Rooms	Remove toilet room to provide 1 accessible stall	\$1,000.00		Superintendent of Schools		
30	High School	56-131			B. Overall Access	B.)Accessible plumbing fixtures or stalls not provided		Priority 5	Toilet or Bathing Rooms	Provide signage directing people to accessible stall	\$180.00		Superintendent of Schools		
32	High School	56-026			B. Overall Access	B.)Accessible plumbing fixtures or stalls not provided	child care	Priority 5	Toilet or Bathing Rooms	Remove rear grab bar and toilet paper to be in compliance	\$600.00		Superintendent of Schools		
50	High School	56-055			B. Overall Access	B.)Accessible plumbing fixtures or stalls not provided	boys toilet room	Priority 5	Toilet or Bathing Rooms	Remove toilet room to provide 1 accessible stall	\$2,000.00		Superintendent of Schools		
107	High School	56-056			B. Overall Access	B.)Accessible plumbing fixtures or stalls not provided	girls toilet	Priority 5	Toilet or Bathing Rooms	Remove toilet room to provide 1 accessible stall	\$2,000.00		Superintendent of Schools		
106	High School	56-087			B. Overall Access	B.)Accessible plumbing fixtures or stalls not provided	a117	Priority 5	Toilet or Bathing Rooms	Remove toilet room to provide 1 accessible stall	\$2,000.00		Superintendent of Schools		
110	High School	56-111			B. Overall Access	F)Rear floor space not provided in toilet room	a17	Priority 5	Toilet or Bathing Rooms	Remove furniture in 3 single use toilet rooms	\$150.00	2019	Superintendent of Schools		
110	High School	56-030			B. Overall Access	F)Rear floor space not provided in toilet room	3131	Priority 5	Toilet or Bathing Rooms	Remove furniture in 3 single use toilet rooms	\$400.00		Superintendent of Schools		
	High School	56-049			B. Overall Access		student fac	Priority 5	Toilet or Bathing Rooms	Relocate rear grab bar and toilet paper to be in compliance			Superintendent of Schools		
38	High School	56-084			F. Lockers	F)Provided in outline non-compliant	girls locker room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection	\$66.00	2019	Superintendent of Schools		
38	High School	56-096			C. Lavatory	F)Exposed plumbing underneath	boys toilet room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection	\$66.00	2019	Superintendent of Schools		
70	High School	56-106			C. Lavatory	F)Exposed plumbing underneath	boys toilet room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection	\$66.00	2019	Superintendent of Schools		
70	High School	56-074			G. Toilet Compartment	Non-compliant rear grab bar	child care	Priority 5	Toilet or Bathing Rooms				Superintendent of Schools		
71	High School	56-014			G. Toilet Compartment	wheelchair		Priority 5	Toilet or Bathing Rooms	Relocate toilet paper dispenser	\$100.00	2019	Superintendent of Schools		
106	High School	56-135			G. Toilet Compartment	compliance issue rear grab bar < 48"	a101	Priority 5	Toilet or Bathing Rooms	Relocate toilet paper dispenser	\$100.00	2019	Superintendent of Schools		
106	High School	56-080			G. Toilet Compartment	F)Rear floor > 48"	boys toilet room	Priority 5	Toilet or Bathing Rooms	Remove toilet room to provide 1 accessible stall	\$1,000.00		Superintendent of Schools		
100	High School	56-089			G. Toilet Compartment		students/faculty	Priority 5	Toilet or Bathing Rooms	Provide signage denoting gender on 2nd and 3rd floor	\$300.00		Superintendent of Schools		
100	High School	56-134			H. Shower Compartment	G)Non-compliant controls location		Priority 5	Toilet or Bathing Rooms	Lower shower control to 48" or lower above the finish floor	\$270.00		Superintendent of Schools		
100	High School	56-133			H. Shower Compartment		girls' shower	Priority 5	Toilet or Bathing Rooms	Lower shower control to 48" or lower above the finish floor	\$50.00	2019	Superintendent of Schools		
108	High School	56-128			K. Lockers	C)Storage < 48" height	girls' locker room	Priority 4	Access to Goods and Services	Provide 30 accessible lockers in the girls' and boys' locker rooms (20 total)	\$15,000.00		Superintendent of Schools		
179	High School	56-130, 5A-129			L. Bench	C)Back support not provided	a101	Priority 4	Access to Goods and Services	Ensure that 1 bench provides compliant back support in the girls' and boys' locker rooms (20 total)	\$600.00		Superintendent of Schools		
180	High School	56-138			A. Drinking Fountain			Priority 6	Additional Access	Lower drinking fountain so that there is 27" clear underneath	\$970.00		Superintendent of Schools		
180	High School	56-072			C. Residential Kitchens & Kitchensettes	A)Toe and knee clearance not provided Non-compliant appliances	C. a108	Priority 6	Additional Access	Remove kitchen to have compliant sink, appliances, work space, and accessories	\$2,090.00		Superintendent of Schools		
181	High School	56-065			C. Residential Kitchens & Kitchensettes		a101	Priority 6	Additional Access	Remove kitchen to have compliant sink, appliances, work space, and accessories	\$2,090.00		Superintendent of Schools		
179	High School	56-059			C. Residential Kitchens & Kitchensettes		culinary arts 101	Priority 6	Additional Access	Remove kitchen to have compliant sink, appliances, work space, and accessories	\$2,090.00		Superintendent of Schools		
179	High School	56-060			C. Residential Kitchens & Kitchensettes		a101	Priority 6	Additional Access	Remove kitchen to have compliant sink, appliances, work space, and accessories	\$2,090.00		Superintendent of Schools		
187	High School	56-067			C. Residential Kitchens & Kitchensettes	Non-compliant appliances	a101, a102	Priority 6	Additional Access	Remove kitchen to have compliant sink, appliances, work space, and accessories			Superintendent of Schools		
179	High School	56-149			Drinks and / Foods	only food > 48"	3131	Priority 3	Approach and Entrance	Provide an accessible route to the playground	\$130.00	2019	Superintendent of Schools		
180	High School	56-049			Drinks and / Foods	only food > 48"	3131	Priority 3	Approach and Entrance	Provide an accessible route to the playground	\$130.00	2019	Superintendent of Schools		
184	High School	56-000			D. Off-Street Parking	A)Not provided		Priority 3	Approach and Entrance	Provide 1 accessible van space	\$870.00		Superintendent of Schools		
180	High School	56-003			F. Ramp (in a Walkway)	B)Running slope or ramp > 1:12		Priority 3	Approach and Entrance	Correct slopes on ramp and repair gap	\$1,925.00		Superintendent of Schools		
180	High School	56-017			H. Entrance	A)Not connected to an accessible route		Priority 3	Approach and Entrance	Provide directional sign to accessible route	\$280.00		Superintendent of Schools		
181	High School	56-082			H. Entrance	B)Not connected to an accessible route		Priority 3	Approach and Entrance	Provide directional sign to accessible route	\$150.00		Superintendent of Schools		
180	High School	56-006			H. Entrance	B)Not connected to an accessible route		Priority 3	Approach and Entrance	Provide directional sign to accessible route	\$150.00		Superintendent of Schools		
180	High School	56-005			H. Entrance	B)Not connected to an accessible route		Priority 3	Approach and Entrance	Provide directional sign to accessible route	\$150.00		Superintendent of Schools		
180	High School	56-038			A. Door	B)Not provide clear width of 32"		Priority 4	Access to Goods and Services	Install a door that provides a clear width of 32"	\$2,500.00		Superintendent of Schools		
180	High School	56-011			A. Door	C)Maneuvering clearance(s) not provided	library	Priority 4	Access to Goods and Services	Allow furniture to provide maneuvering clearance	\$50.00	2019	Superintendent of Schools		
180	High School	56-029			A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Allow furniture to provide maneuvering clearance	\$150.00	2019	Superintendent of Schools		
180	High School	56-029			A. Door	C)Maneuvering clearance(s) not provided		Priority 4	Access to Goods and Services	Allow furniture to provide maneuvering clearance	\$150.00	2019	Superintendent of Schools		
180	High School	56-034			A. Door	C)Maneuvering clearance(s) not provided	classroom on 2	Priority 4	Access to Goods and Services	Allow furniture to provide maneuvering clearance	\$0.00		Superintendent of Schools		

473	Hopewell Elementary School	19-010		A. Door	D)Measuring clearance(s) not provided at recess	library	Priority 4	Access to Goods and Services	Consider installing an automatic door opener if this is the door that provides the library.	\$1,500.00			Superintendent of Schools		
474	Hopewell Elementary School	19-016		A. Door	B)Door requires 15 degrees	staff toilet room	Priority 4	Access to Goods and Services	Replace door hardware	\$441.00			Superintendent of Schools		
475	Hopewell Elementary School	19-020		A. Door	A)Target not securely attached	principal office	Priority 4	Access to Goods and Services	When replacement occurs, provide a door with a door alarm system	\$0.00			Superintendent of Schools		
487	Hopewell Elementary School	19-025		A. Door	A)Vision light located <48" AFF B)Hardware inoperable C)Measuring clearance(s) not provided at recess	classroom on 2	Priority 4	Access to Goods and Services	Secure floor and lockable, no action needed until it is made accessible	\$0.00			Superintendent of Schools		
476	Hopewell Elementary School	19-031		A. Door		library	Priority 4	Access to Goods and Services	Maintain the door hardware	\$300.00			Superintendent of Schools		
478	Hopewell Elementary School	19-024		B. Stairway (Interior)	A)Handrails do not extend 12" from stairs		Priority 4	Access to Goods and Services	Install 1.7" extensions at top and bottom	\$280.00			Superintendent of Schools		
481	Hopewell Elementary School	19-032		D. Interior Route	D)Surface not stable, firm, and slip-resistant		Priority 2	Safety	Secure all weather mats and carpets with industrial strength double click tape	\$200.00	2016	Dec 10	Superintendent of Schools	completed	
485	Hopewell Elementary School	19-033		D. Interior Route	D)Surface not stable, firm, and slip-resistant		Priority 2	Safety	Secure all weather mats and carpets with industrial strength double click tape	\$200.00	2016	Dec 10	Superintendent of Schools	completed	
486	Hopewell Elementary School	19-043		D. Interior Route	F)Door slope >1:48	girls toilet room	Priority 4	Access to Goods and Services	Repair excessive cross slope at girl's toilet door	\$0.00			Superintendent of Schools		
482	Hopewell Elementary School	19-030		D. Interior Route	G)Changes in level >1/4"	boys toilet room	Priority 4	Access to Goods and Services	Make minor repairs to address	\$300.00			Superintendent of Schools		
483	Hopewell Elementary School	19-045		D. Interior Route	G)Changes in level >1/4"	early intervention clinic	Priority 4	Access to Goods and Services	Make minor repairs to address	\$300.00			Superintendent of Schools		
484	Hopewell Elementary School	19-046		D. Interior Route	H)Bowl(s) changes in level >1/2"	early intervention clinic	Priority 4	Access to Goods and Services	Make minor repairs to address high curb(s) change in level	\$300.00			Superintendent of Schools		
489	Hopewell Elementary School	19-039		D. Interior Route	I)Door width <60"	early vision	Priority 4	Access to Goods and Services	Rearrange furniture to provide a 32" wide clear width	\$50.00	2016	Feb 10	Superintendent of Schools	completed	
490	Hopewell Elementary School	19-026		F. Dining or Work Surface	A)Number of tables provided B)Door frame clearance at tables not recorded	classroom	Priority 4	Access to Goods and Services	Provide 3 accessible table with knee clearance	\$500.00	2016		Superintendent of Schools		
491	Hopewell Elementary School	19-022		F. Dining or Work Surface	C)Top of dining surface <28" or 34"	library	Priority 4	Access to Goods and Services	Provide 3 accessible table with knee clearance	\$500.00	2016		Superintendent of Schools		
492	Hopewell Elementary School	19-021		F. Dining or Work Surface	C)Top of dining surface <28" or 34"	S	Priority 4	Access to Goods and Services	Provide 3 accessible table with knee clearance	\$500.00	2016		Superintendent of Schools		
493	Hopewell Elementary School	19-042		I. Signage	A)Not provided	girls toilet room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00			Superintendent of Schools		
494	Hopewell Elementary School	19-007		I. Signage	A)Bowl(s), misplaced C)Bowl(s), non-compliant	lobby	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00			Superintendent of Schools		
495	Hopewell Elementary School	19-027		I. Signage	A)Bowl(s), misplaced C)Bowl(s), non-compliant	lobby	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00			Superintendent of Schools		
496	Hopewell Elementary School	19-036		I. Signage	A)Bowl(s), misplaced C)Bowl(s), non-compliant D)Bowl(s) <48" or >60" above ground E)Sign not recorded on the latch side of the door		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00			Superintendent of Schools		
477	Hopewell Elementary School	19-008		I. Signage	A)Bowl(s), misplaced C)Bowl(s), non-compliant E)Sign not recorded on the latch side of the door	principal office	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00			Superintendent of Schools		
488	Hopewell Elementary School	19-023		I. Signage	A)Bowl(s), misplaced C)Bowl(s), non-compliant E)Sign not recorded on the latch side of the door	boys toilet room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door	\$150.00			Superintendent of Schools		
479	Hopewell Elementary School	19-014		B. Overall Access	A)Turning space not provided	staff toilet room	Priority 5	Toilet or Bathing Rooms	Enlarge single user toilet room, or provide it in a different location, if modifications are not feasible, provide signage directing people to accessible toilet rooms	\$11,700.00			Superintendent of Schools		
480	Hopewell Elementary School	19-037		B. Overall Access	A)Turning space not provided B)Clear floor space not provided in toilet room	nurse's room	Priority 5	Toilet or Bathing Rooms	Enlarge single user toilet room, or provide it in a different location, if modifications are not feasible, provide signage directing people to accessible toilet rooms	\$11,700.00			Superintendent of Schools		
486	Hopewell Elementary School	19-044		B. Overall Access	B)Accessible plumbing fixtures or stalls not provided	girls toilet room	Priority 5	Toilet or Bathing Rooms	Remove toilet room to have 1 accessible stall and 1 ambulatory accessible stall	\$4,600.00			Superintendent of Schools		
497	Hopewell Elementary School	19-019	FD-7286	C. Lavatory	F)Bowl(s) at urinal underneath	boys toilet room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection	\$66.00	2016		Superintendent of Schools		
498	Hopewell Elementary School	19-015	FD-7287 Insulate pipes	C. Lavatory	E)Bowl(s) plumbing underneath B)Not above lavatory w/ reflective surface >40"	staff toilet room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection and cover mirror in bottom surface is at 40" or lower	\$266.00	2016		Superintendent of Schools		
489	Hopewell Elementary School	19-021		G. Toilet Compartment	F)Bowl(s) measuring clearances	boys toilet room	Priority 5	Toilet or Bathing Rooms	Enlarge toilet compartment to be 60" wide and not reduce side grab bar per ADA and ANSI	\$1,700.00			Superintendent of Schools		
481	Hopewell Elementary School	19-042		H. Toilet Compartment	B)Door w/ malfunctioning self-closing hinge	boys toilet room	Priority 5	Toilet or Bathing Rooms	Repair or replace self-closing hinge	\$100.00			Superintendent of Schools		
490	Hopewell Elementary School	19-030	FD-7288 Insulate pipes	H. Sink	E)Bowl(s) plumbing underneath sink A)Not above lavatory w/ reflective surface >40"	hallway	Priority 6	Additional Access	Ensure that one sink has 27" clear underneath and that its pipes are protected	\$1,636.00			Superintendent of Schools		
488	Martin Middle School	16-002		B. Entrance	F)Target not securely attached	lobby	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec 10	Superintendent of Schools	completed	
485	Martin Middle School	16-007		A. Door	A)At least one leaf is non-compliant	library	Priority 4	Access to Goods and Services	Replace all double-leaf doors with 36-inch wide doors. Alternatively, keep them open during regular hours.	\$1,550.00			Superintendent of Schools		
479	Martin Middle School	16-023		A. Door	B)Door, not provide clear width of 32" A)Smooth surface not provided at bottom 10" B)Hardware inoperable	Nurse's Room	Priority 4	Access to Goods and Services	Install a door that provides a clear width of 32". Install compliant hardware and a smooth surface on the push side of the door.	\$3,041.00			Superintendent of Schools		
484	Martin Middle School	16-020		A. Door	C)Measuring clearance(s) not provided	Girls Toilet Room	Priority 4	Access to Goods and Services	Install an automatic door opener on the inside of the toilet room	\$1,500.00			Superintendent of Schools		
486	Martin Middle School	16-048		A. Door	C)Measuring clearance(s) not provided	Special Ed Room	Priority 4	Access to Goods and Services	Install an automatic door opener on the inside of the classroom	\$1,500.00			Superintendent of Schools		
487	Martin Middle School	16-009		A. Door	B)Hardware inoperable	102	Priority 4	Access to Goods and Services	Install compliant door hardware	\$441.00			Superintendent of Schools		
488	Martin Middle School	16-009		A. Door	B)Hardware inoperable	100	Priority 4	Access to Goods and Services	Install compliant door hardware	\$441.00			Superintendent of Schools		
489	Martin Middle School	16-024		A. Door	B)Hardware inoperable	11 doors	Priority 4	Access to Goods and Services	Install compliant door hardware	\$441.00			Superintendent of Schools		
482	Martin Middle School	16-026		A. Door	B)Hardware inoperable	5 doors	Priority 4	Access to Goods and Services	Install compliant door hardware	\$441.00			Superintendent of Schools		
480	Martin Middle School	16-016	FD-7549	A. Door	K)Door requires 15 pounds of force to open	Girls Toilet Room	Priority 4	Access to Goods and Services	Adjust doors so interior doors do not require more than 5 pounds of force. When adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door operators.	\$50.00	2016	Feb 10	Superintendent of Schools	completed	
486	Martin Middle School	16-046		B. Stairway (Interior)	A)Handrails have non-compliant cross section B)Handrails do not extend 12" from stairs	Auditorium	Priority 4	Access to Goods and Services	Install compliant handrails with extensions	\$480.00			Superintendent of Schools		
485	Martin Middle School	16-040		B. Stairway (Interior)	A)Handrails do not extend 12" from stairs B)Door ramp reflect not visible, firm, and slip-resistant A)Handrails do not extend 12" past top & bottom B)Banding length <60"	Girls Locker Room	Priority 4	Access to Goods and Services	Install 1.7" extensions at top and bottom	\$280.00			Superintendent of Schools		
486	Martin Middle School	16-028		C. Ramp (Interior)	A)Banding length <60"		Priority 4	Access to Goods and Services	Repair ramp when planning future renovations.	\$0.00			Superintendent of Schools		
482	Martin Middle School	16-010		D. Interior Route	A)Target not securely attached	library	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec 10	Superintendent of Schools	completed	
480	Martin Middle School	16-024		D. Interior Route	C)Obstructed by protruding objects	Girls Toilet Room	Priority 2	Safety	Relocate objects	\$60.00	2016	Dec 10	Superintendent of Schools	completed	
482	Martin Middle School	16-025		D. Interior Route	D)Surface not stable, firm, and slip-resistant	room 113	Priority 2	Safety	Secure all weather mats with industrial-strength double-click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Dec 10	Superintendent of Schools	completed	

400	Martin Middle School	56-009	E. Service Counter	B. Counter >36" high C. Barbed approach - surface <50" long	Library	Priority 4	Access to Goods and Services	Modify counters on each office with public interface so that they are accessible to the mainline, provide an auxiliary counter no higher than 48" above the floor in close proximity to the main counter, or provide equivalent facilitation. Equivalent facilitation may be provided in the form of a folding shelf attached to the main counter, an auxiliary table nearby, a signpost made available to the public, or other means.	\$640.00	2014	Superintendent of Schools		
401	Martin Middle School	56-008	F. Dining or Work Surface	F. Floor or work surface at table not provided	Library	Priority 4	Access to Goods and Services	Provide 1 accessible workstation.	\$500.00	2014	Superintendent of Schools		
402	Martin Middle School	56-081	F. Dining or Work Surface	F. Floor of dining surface 48" or 14"	Science Lab	Priority 4	Access to Goods and Services	Provide 1 accessible workstation.	\$500.00	2014	Superintendent of Schools		
403	Martin Middle School	56-013, 56-014	E. Elevator	A. Elevator with buttons 48" B. Handway signs > 60" to centerline E. Elevator and visible indicators not provided Emergency communication system 48" F. Elevator car control 48"	S.	Priority 4	Access to Goods and Services	Remove floor to be accessible and install glass handway signs at 60" to centerline. When making future renovations, install Braille, and ensure call button.	\$1,150.00		Superintendent of Schools		
404	Martin Middle School	56-047	I. Assembly Area	B. Wheelchair route meeting circulation paths D. Supervision not provided E. Number of designated wheelchair spaces	Auditorium	Priority 4	Access to Goods and Services	Provide 2 accessible seats in front and ensure that 1% of aisle seats have accessible arms.			Superintendent of Schools		
405	Martin Middle School	56-004	J. Signage	B. Provided, misplaced C. Provided, non-compliant	Guidance Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
406	Martin Middle School	56-005	J. Signage	B. Provided, misplaced C. Provided, non-compliant	Main Office	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
407	Martin Middle School	56-011	J. Signage	B. Provided, misplaced C. Provided, non-compliant E. Entrance > 60" above ground	Student Activity Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
408	Martin Middle School	56-006	J. Signage	B. Provided, misplaced C. Provided, non-compliant E. Entrance > 60" above ground	Library	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
409	Martin Middle School	56-040	J. Signage	B. Provided, misplaced C. Provided, non-compliant	Boys Toilet Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
410	Martin Middle School	56-005	J. Signage	B. Provided, misplaced C. Provided, non-compliant	Main Office	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
411	Martin Middle School	56-039	J. Signage	B. Provided, misplaced C. Provided, non-compliant	Girls Toilet Room	Priority 4	Access to Goods and Services	Replace sign so that tactile characters are between 48" and 60" above finish floor.	\$50.00		Superintendent of Schools		
412	Martin Middle School	56-050	J. Signage	F. Sign not provided on the latch side of the door B. Provided, non-compliant E. Entrance > 60" above ground F. Missing or non-compliant USA	Special Ed Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
413	Martin Middle School	56-052	J. Signage	F. Sign not provided on the latch side of the door B. Provided, misplaced C. Provided, non-compliant E. Entrance > 60" above ground	Girls Toilet Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
414	Martin Middle School	56-015	J. Signage	F. Sign not provided on the latch side of the door B. Provided, misplaced C. Provided, non-compliant	Girls Toilet Room	Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
415	Martin Middle School	56-013	J. Signage	F. Sign not provided on the latch side of the door B. Provided, misplaced C. Provided, non-compliant	Cafeteria	Priority 4	Access to Goods and Services	Provide a compliant sign. Ensure that center line of the sign is 60" above the finish floor on the latch side of the door.	\$150.00		Superintendent of Schools		
416	Martin Middle School	56-035	J. Signage	B. Provided, non-compliant		Priority 4	Access to Goods and Services	Install an ADA-compliant sign on the latch side of the door.	\$150.00		Superintendent of Schools		
417	Martin Middle School	56-021	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Nurse's Room	Priority 5	Toilet or Bathing Rooms	Provide signage from 2 non-accessible toilets in nurse's office directing people to an accessible toilet.	\$300.00		Superintendent of Schools		
418	Martin Middle School	56-049	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Special Ed. Toilet Room	Priority 5	Toilet or Bathing Rooms	Provide signage to an accessible toilet room.	\$150.00		Superintendent of Schools		
419	Martin Middle School	56-051	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Special Ed. Toilet Room	Priority 5	Toilet or Bathing Rooms	Provide signage to an accessible toilet room.	\$150.00		Superintendent of Schools		
420	Martin Middle School	56-037	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Girls Locker Room	Priority 5	Toilet or Bathing Rooms	Combine stalls to provide 1 accessible stall.	\$2,950.00		Superintendent of Schools		
421	Martin Middle School	56-036	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Girls Locker Room	Priority 5	Toilet or Bathing Rooms	Combine stalls to provide 1 accessible stall. Ensure that 1 changing room is made accessible.	\$6,400.00		Superintendent of Schools		
422	Martin Middle School	56-042	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Boys Locker Room/Office	Priority 5	Toilet or Bathing Rooms	Combine stalls to provide 1 accessible stall.	\$2,950.00		Superintendent of Schools		
423	Martin Middle School	56-054	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Boys	Priority 5	Toilet or Bathing Rooms	Combine stalls to provide 1 accessible stall.	\$2,950.00		Superintendent of Schools		
424	Martin Middle School	56-056	B. Overall Access	A. Barrier space not provided B. Accessible plumbing fixture or stalls not provided	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Combine stalls to provide 1 accessible stall.	\$2,950.00		Superintendent of Schools		
425	Martin Middle School	56-038	C. Lavatory	B. Row or knee clearances not provided	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Install 1 compliant lavatory with toe and knee clearances.	\$3,030.00		Superintendent of Schools		
426	Martin Middle School	56-057	C. Lavatory	B. Row or knee clearances not provided	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Install 1 compliant lavatory with toe and knee clearances.	\$3,030.00		Superintendent of Schools		
427	Martin Middle School	56-005	C. Lavatory	A. Barrier floor space not provided B. Row or knee clearances not provided	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Remove apron under counter, and protect pipes. (Pipe's size if it does not have 2" clear underneath).	\$180.00		Superintendent of Schools		
428	Martin Middle School	56-018	C. Lavatory	A. Barrier floor space not provided at lavatory	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Install 1 compliant lavatory with toe and knee clearances.	\$3,030.00		Superintendent of Schools		
429	Martin Middle School	56-034	C. Lavatory	F. Exposed plumbing underneath	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection.	\$66.00	2014	Superintendent of Schools		
430	Martin Middle School	56-044	C. Lavatory	F. Exposed plumbing underneath	Boys Locker Room/Office	Priority 5	Toilet or Bathing Rooms	Provide pipe protection.	\$66.00	2014	Superintendent of Schools		
431	Martin Middle School	56-011	C. Lavatory	F. Exposed plumbing underneath E. Mirror above lavatory w/ reflective surface > 40"	Boys Locker Room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection and lower mirror so bottom surface is at 40" or lower.	\$266.00	2014	Superintendent of Schools		
432	Martin Middle School	56-022	C. Lavatory	Clear floor space not provided - toe or knee clearances not provided Excess at plumbing underneath, mirror > 40"	Nurse room	Priority 5	Toilet or Bathing Rooms				Superintendent of Schools		
433	Martin Middle School	56-064	E. Urinal	A. Min > 17" height C. Back controls, too high or not properly located	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower urinal so that its rim is no higher than 17" above the floor.	\$1,550.00		Superintendent of Schools		
434	Martin Middle School	56-030	E. Urinal	A. Min > 17" height C. Back controls, too high or not properly located	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower urinal so that its rim is no higher than 17" above the floor and relocate the flush valve.	\$1,750.00		Superintendent of Schools		
435	Martin Middle School	56-043	E. Urinal	A. Min > 17" height C. Back controls, too high or not properly located	Boys Locker Room/Office	Priority 5	Toilet or Bathing Rooms	Lower urinal so that its rim is no higher than 17" above the floor.	\$1,750.00		Superintendent of Schools		
436	Martin Middle School	56-055	E. Urinal	A. Min > 17" height C. Back controls, too high or not properly located	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower urinal so that its rim is no higher than 17" above the floor.	\$1,750.00		Superintendent of Schools		
437	Martin Middle School	56-029	G. Total Compartment	F. Back controls, too high or not properly located	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Install compliant grab bar and accessible back control.	\$300.00		Superintendent of Schools		
438	Martin Middle School	56-033	G. Total Compartment	C. Back compliant side or rear grab bars F. Back controls, too high or not properly located	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Install compliant grab bar and accessible back control.	\$500.00		Superintendent of Schools		
439	Martin Middle School	56-063	G. Total Compartment	C. Back compliant side or rear grab bars F. Back controls, too high or not properly located	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Install side grab bar and compliant toilet paper dispenser.	\$500.00		Superintendent of Schools		
440	Martin Middle School	56-017	G. Total Compartment	C. Back compliant side or rear grab bars F. Back controls, too high or not properly located	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Install compliant grab bar and accessible toilet paper.	\$350.00		Superintendent of Schools		
441	Martin Middle School	56-046	G. Total Compartment	E. Back compliant toilet paper dispenser	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Install compliant toilet paper dispenser.	\$200.00	2014	Superintendent of Schools		
442	Martin Middle School	56-041	L. Bench	C. Back support not provided	Boys Locker Room/Office	Priority 4	Access to Goods and Services	Provide 1 bench with back support.	Labor		Superintendent of Schools		
443	Martin Middle School	56-045	A. Drinking Fountain	A. Barrier floor space not provided at drinking fountain	Boys Locker Room/Office	Priority 6	Additional Access	Raise compliant drinking fountain on the first floor to have 27" clear underneath. Provide signage at standing drinking fountains directing users to accessible drinking fountain.	\$1,120.00		Superintendent of Schools		
444	Martin Middle School	56-058	A. Drinking Fountain	A. Barrier floor space not provided at drinking fountain	Corridor	Priority 6	Additional Access	Raise compliant drinking fountain on the 2nd floor to have 27" clear underneath. Provide signage at standing drinking fountains directing users to accessible drinking fountain.	\$1,120.00		Superintendent of Schools		
445	Martin Middle School	56-024	A. Drinking Fountain	A. Barrier floor space not provided at drinking fountain C. Spout > 36" height	Corridor	Priority 6	Additional Access	Provide signage at fountain directing users to accessible drinking fountain.	\$150.00		Superintendent of Schools		
446	Martin Middle School	56-052	B. Sink	A. Barrier floor space not provided at sink B. Row and knee clearances not provided C. Min or counter > 34" D. Back compliant faucets	Special Ed Room	Priority 6	Additional Access	Install compliant faucets.	\$630.00		Superintendent of Schools		
447	Martin Middle School	56-062	B. Sink	B. Row and knee clearances not provided C. Min or counter > 34" D. Back compliant faucets	Lab	Priority 6	Additional Access	Install 1 accessible sink in 220, 218, 214, remove cabinet and lower sink to 34" above finish floor, protect floor.	\$6,708.00		Superintendent of Schools		
448	Martin Middle School	56-027	M. Storage	C. Backs to shelves non-compliant		Priority 6	Additional Access	Install 1 compliant locker.	\$500.00		Superintendent of Schools		
449	Mulachay Elementary School	513-000	H. Entrance	A. Surface not stable, firm, and slip-resistant	Lobby	Priority 3	Approach and Entrance	Secure all weather mats with industrial strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$300.00	2014, January 2016	Superintendent of Schools	Completed	None
450	Mulachay Elementary School	513-004	A. Door	B. Door not provide clear width of 32"	Cafeteria	Priority 4	Access to Goods and Services	Install a door that provides a clear width of 32".	\$2,500.00		Superintendent of Schools		
451	Mulachay Elementary School	513-022	A. Door	B. Door not provide clear width of 32" C. Backswinging door(s) not provided D. Backswing responsible M. Smooth surface not provided at bottom 10"	Nurse's Office	Priority 4	Access to Goods and Services	Install a door with 32" of clear space at minimum and an automatic door opener.	\$2,570.00		Superintendent of Schools		



710	Mulakey Elementary School	513-054 a		C. Lavatory	F Mirror above lavatory w/ reflective surface > 40"	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$266.00	2016	Superintendent of Schools		
712	Mulakey Elementary School	513-054 b		C. Lavatory	F Exposed plumbing underneath	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection .	\$266.00	2016	Superintendent of Schools		
713	Mulakey Elementary School	513-053 a		C. Lavatory	F Exposed plumbing underneath	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Provide pipe protection	\$341.00	2016	Superintendent of Schools		
716	Mulakey Elementary School	513-053 b		C. Lavatory	F Mirror above lavatory w/ reflective surface > 40"	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower mirror so bottom surface is at 40" or lower.	\$341.00	2016	Superintendent of Schools		
711	Mulakey Elementary School	513-053 c		C. Lavatory	A Mirror floor space not provided at lavatory B Mirror knee clearance not provided	Girls Toilet Room	Priority 5	Toilet or Bathing Rooms	Remove wooden box so that 1 lavatory is accessible	\$341.00	2016	Superintendent of Schools		
719	Mulakey Elementary School	513-043		D. Toilet	A Obstruct compliant side grab bar B Non-compliant side grab bar	Accessible Toilet Room	Priority 5	Toilet or Bathing Rooms	Install compliant grab bars	\$600.00		Superintendent of Schools		
695	Mulakey Elementary School	513-015		E. Urinal	A Mirror > 12" height C Flush controls too high or not properly located	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower urinal so that its rim is no higher than 12" above the floor, and relocate flush controls	\$1,750.00		Superintendent of Schools		
720	Mulakey Elementary School	513-032		C. Urinal	A Mirror > 12" height C Flush controls too high or not properly located B Mirror floor space not provided at urinal	Boys Toilet Room	Priority 5	Toilet or Bathing Rooms	Lower urinal so that its rim is no higher than 12" above the floor, and relocate flush controls, enlarge partition to provide 30" clear" centered on urinal	\$2,250.00		Superintendent of Schools		
715	Mulakey Elementary School	513-036		A. Drinking Fountain	A Mirror floor space not provided at drinking fountain	Corridor	Priority 6	Additional Access	Provide sign directing people to located accessible fountain on floor.	\$150.00		Superintendent of Schools		
718	Mulakey Elementary School	513-060		A. Drinking Fountain	A Mirror floor space not provided at drinking fountain	Corridor	Priority 6	Additional Access	Raise fountain so that there is 27" clear underneath and enlarge ramp as well as that it is 36" wide	\$1,036.00		Superintendent of Schools		
697	Mulakey Elementary School	513-007		A. Drinking Fountain	A Mirror floor space not provided at drinking fountain C Mirror > 36" height	Lobby	Priority 6	Additional Access	Replace fountain with an accessible fountain	\$1,950.00		Superintendent of Schools		
717	Mulakey Elementary School	513-049		A. Drinking Fountain	A Mirror floor space not provided at drinking fountain C Mirror > 36" height	Corridor	Priority 6	Additional Access	Provide sign directing people to located accessible fountain on floor.	\$150.00		Superintendent of Schools		
714	Mulakey Elementary School	513-028		B. Sink	A Mirror floor space not provided at sink B Mirror knee clearances not provided	First Grade	Priority 6	Additional Access	Remove cabinet under sink	\$600.00		Superintendent of Schools		
696	Mulakey Elementary School	p1020345		D. Interior Route	D Surface not stable, firm, and slip-resistant	N10	Priority 2	Safety	Secure all weather mats with industrial strength double click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	See 10	Superintendent of Schools	completed
692	Mulakey Elementary School	p1020346		D. Interior Route	D Surface not stable, firm, and slip-resistant	N09	Priority 2	Safety	Secure all weather mats with industrial strength double click tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	See 10	Superintendent of Schools	completed
710	Mulakey Elementary School	513-021 a		B. Sink	A Mirror floor space not provided at sink	Nurse's Office	Priority 6	Additional Access	Move sink from wall so that the centerline of the faucet is 15", and relocate trash can	\$1,686.00		Superintendent of Schools		
710	Mulakey Elementary School	513-021 b		B. Sink	F Exposed plumbing underneath sink	Nurse's Office	Priority 6	Additional Access	Protect plumbing	\$1,686.00		Superintendent of Schools		
216	Parker Middle School	56-055		B. Curb Ramp	C Mirror in operating working condition		Priority 3	Approach and Entrance	Ensure curb ramps are maintained in <del>working condition</del>	\$300.00		Superintendent of Schools		
211	Parker Middle School	56-061		B. Curb Ramp			Priority 3	Approach and Entrance	Ensure curb ramps are maintained in <del>working condition</del>	\$300.00		Superintendent of Schools		
222	Parker Middle School	56-060		B. Curb Ramp			Priority 3	Approach and Entrance	Ensure curb ramps are maintained in <del>working condition</del>	\$300.00		Superintendent of Schools		
201	Parker Middle School	56-059		C. Accessible Route to Entrance			Priority 3	Approach and Entrance	Add concrete to correct excessive slope	\$465.00		Superintendent of Schools		
223	Parker Middle School	56-058		D. Off-Street Parking Spaces	C Mirror aisle width < 60" wide		Priority 3	Approach and Entrance	Enlarge access aisle	\$200.00		Superintendent of Schools		
217	Parker Middle School	56-056		D. Off-Street Parking Spaces			Priority 3	Approach and Entrance	Provide sign and enlarge space and access aisle	\$870.00		Superintendent of Schools		
208	Parker Middle School	56-057		D. Off-Street Parking Spaces			Priority 3	Approach and Entrance	Provide sign	\$200.00		Superintendent of Schools		
214	Parker Middle School	56-054		F. Ramp (in a Walkway)			Priority 3	Approach and Entrance	Ensure that handrails are provided on <del>both sides of the ramp</del>	\$1,020.00		Superintendent of Schools		
216	Parker Middle School	56-006		A. Door	C Mirror moving clearances) not provided	library	Priority 4	Access to Goods and Services	Relocate furniture to provide <del>minimum clearances</del>	\$50.00	2016	Superintendent of Schools		
176	Parker Middle School	56-016		A. Door	C Mirror moving clearances) not provided	art	Priority 4	Access to Goods and Services	Relocate furniture to provide <del>minimum clearances</del>	\$50.00	2016	Superintendent of Schools		
216	Parker Middle School	56-019		A. Door	C Mirror moving clearances) not provided	nurse station	Priority 4	Access to Goods and Services	Relocate furniture to provide <del>minimum clearances</del>	\$50.00	2016	Superintendent of Schools		
191	Parker Middle School	56-021		A. Door	C Mirror moving clearances) not provided	nurse	Priority 4	Access to Goods and Services	Relocate furniture to provide <del>minimum clearances</del>	\$50.00	2016	Superintendent of Schools		
213	Parker Middle School	56-012		A. Door	C Mirror moving clearances) not provided		Priority 4	Access to Goods and Services	Relocate furniture to provide <del>minimum clearances</del>	\$50.00	2016	Superintendent of Schools		
169	Parker Middle School	56-002		A. Door	K Mirror requires >15 pounds of force to open		Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door openers.	\$50.00	2016	See 10	Superintendent of Schools	completed
190	Parker Middle School	560020		A. Door	K Mirror requires >15 pounds of force to open	practice rooms	Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door openers.	\$50.00	2016	See 10	Superintendent of Schools	completed
168	Parker Middle School	56-034		A. Door	K Mirror requires >15 pounds of force to open		Priority 4	Access to Goods and Services	Adjust closers to interior doors do not require more than 5 pounds of force. Where adjusting the required force is not possible, either keep heavy doors open during regular hours or install automatic door openers.	\$50.00	2016	See 10	Superintendent of Schools	completed
175	Parker Middle School	56-017		A. Door	N Mirror light located < 43" AFF M Mirror surface not provided at bottom 10"		Priority 4	Access to Goods and Services	Provide a smooth surface on the push side. When renovations occur, select a door with a lower vision light.	\$60.00	2016	Superintendent of Schools		
166	Parker Middle School	56-025		A. Door	N Mirror light located < 43" AFF M Mirror surface not provided at bottom 10"		Priority 4	Access to Goods and Services	Provide a smooth surface on the push side. When renovations occur, select a door with a lower vision light.	\$60.00	2016	Superintendent of Schools		
216	Parker Middle School	56-053		C. Ramp (Interior)	B Mirroring slope > 1:12	camp to library	Priority 4	Access to Goods and Services	When renovations occur, adjust slope of ramps	\$0.00		Superintendent of Schools		
188	Parker Middle School	56-001		C. Ramp (Interior)	Handrails not continuous where required	camp to library	Priority 4	Access to Goods and Services				Superintendent of Schools		
204	Parker Middle School	56-022		D. Interior Route	C Mirror obstructed by protruding objects	corridor	Priority 2	Safety	Move objects or install cane detectable barriers	\$50.00	2016	Superintendent of Schools		
217	Parker Middle School	56-048		D. Interior Route	C Mirror obstructed by protruding objects	boys	Priority 2	Safety	Move objects or install cane detectable barriers	\$50.00	2016	Superintendent of Schools		
211	Parker Middle School	56-050		D. Interior Route	C Mirror obstructed by protruding objects	girls	Priority 2	Safety	Move objects or install cane detectable barriers	\$50.00	2016	Superintendent of Schools		
201	Parker Middle School	56-005		D. Interior Route	L Mirror width < 36"	library reading area	Priority 4	Access to Goods and Services	Relocate furniture to provide 36" clear width	\$50.00	2016	Superintendent of Schools		
207	Parker Middle School	56-034		D. Interior Route	L Mirror width < 36"		Priority 4	Access to Goods and Services	Relocate furniture to provide 36" clear width	\$50.00	2016	Superintendent of Schools		
198	Parker Middle School	56-007		D. Interior Route		boys	Priority 4	Access to Goods and Services	Relocate paper towels away from accessible rib	\$50.00	2016	Superintendent of Schools		
190	Parker Middle School	56-049		D. Interior Route		girls	Priority 4	Access to Goods and Services	Relocate paper towels away from accessible rib	\$50.00	2016	Superintendent of Schools		
190	Parker Middle School	56-031		F. Dining or Work Surface	C Mirror least one or 5% accessible not provided	cafeteria	Priority 4	Access to Goods and Services	Provide at least 1 or 5% accessible tables	\$500.00	2016	Superintendent of Schools		
198	Parker Middle School	56-018		F. Dining or Work Surface	C Mirror least one or 5% accessible not provided B Mirror knee clearance at tables not provided	computer room	Priority 4	Access to Goods and Services	Provide at least 1 or 5% accessible tables	\$500.00	2016	Superintendent of Schools		
189	Parker Middle School	56-004		F. Dining or Work Surface	B Mirror knee clearance at tables not provided	library	Priority 4	Access to Goods and Services	Provide at least 1 or 5% accessible tables	\$500.00	2016	Superintendent of Schools		
215	Parker Middle School	56-028		F. Dining or Work Surface	B Mirror knee clearance at tables not provided		Priority 4	Access to Goods and Services	Provide at least 1 or 5% accessible tables	\$500.00	2016	Superintendent of Schools		
221	Parker Middle School	56-030		I. Signage	B Mirror provided, misplaced C Braille characters < 48" or > 60" above ground		Priority 4	Access to Goods and Services	Replace sign so that tactile characters are between 48" and 60" above finish floor	\$50.00		Superintendent of Schools		
205	Parker Middle School	56-033		I. Signage	C Braille characters < 48" or > 60" above ground	cafeteria	Priority 4	Access to Goods and Services	Replace sign so that tactile characters are between 48" and 60" above finish floor	\$50.00		Superintendent of Schools		

[illegible]